


2007 <http://mlab.taik.fi/paja>
MEMSIC2125 Accelerometer



A wrong circuit layout might burn the sensor!!